

**Interstate Diesel of Idaho LLC**  
 112 West 35th Street  
 Garden City, ID 83714  
 info@interstatedieselidaho.com  
 (208) 809-0305



**Invoice:** 2975  
**Date:** 12/12/2023

**Bill To**  
 ASTEGOS

**Remit Payment To**  
 Interstate Diesel of Idaho LLC,  
 112 West 35th Street  
 Garden City, ID 83714

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2706	COD	12/12/2023	ASTEGOS		Lawrence, Bailey	N/A

Item	Description	Quantity	Rate	Amount
<b>Drive to unit</b>				
Labor	Drive to unit (Service Call)	1.00000	\$185.00	\$185.00
Mileage		2.20000	\$2.50	\$5.50
Service Call		1.0000	\$175.00	\$175.00
			<b>Subtotal</b>	\$365.50

**Complaint:** GET TRUCK STARTED

**Cause:** Customer request

Labor	<b>Correction:</b> Electrical System / Battery / Locate the truck. Check to see if truck will start. Truck will not crank. Check battery voltage. Batteries have 2 volts in them. Will need to return to the shop to get the jump box to see if the truck will start. Inspected the engine compartment. Found that the fuel filter is full of water. Truck will need a complete service and thaw out inside the shop to drain the air system. Packed up and returned to the shop. The repair is complete. - Completed: 12/12/2023	1.00000	\$185.00	\$185.00
			<b>Subtotal</b>	\$185.00

**Complaint:** SERVICE, INSPECTION, TRUCK NOT BUILDING PRESSURE.

**Cause:** Customer request

(Inspection)

Labor	<b>Correction:</b> Engine / Filters / Drain engine oil and remove oil filters. Clean filter mating surface and prep new filters for install. Install new oil filters. Clean drain plug and torque to spec. Fill oil system with fresh oil. Start engine and allow to idle for a couple minutes. Shut off and let sit. Check and adjust oil level as needed. Drain fuel from glass fuel filter. Found water in fuel filter. Remove glass fuel filter. Clean mating surface. Install new fuel filter.	7.24000	\$145.00	\$1,049.80
-------	--	---------	----------	------------

Item	Description	Quantity	Rate	Amount
	<p>Remove spin on fuel filter. Found filter full of water and rust. Pre-fill and install new fuel filter. Prime fuel system. Remove air filter and inspect. Found air filter dirty and in need of replacement. Install new air filter into housing. Install housing cap and secure. Grease chassis. Adjust brakes. Check lights. Found marker lights inop. Check wiper and washer operation. Found wiper blades ripped and washer inop. Found wiper switch knob missing.</p> <p>Check power steering fluid condition and level. Found low.</p> <p>level low. Top off power steering fluid. Check and top off coolant level. Perform visual inspection on truck. Found all OK. Apply service sticker to windshield. Drain air tank and test air system. Found moisture in tank. Blow out air tank and remove moisture.</p> <p>Allow tank to drain overnight. Re-test for proper operation. Found ball valve at air tank leaking air. Remove and replace ball valve.</p> <p>Test system. Found air system working properly. Service complete.</p>			
	<p>Check fuses for washer motor operation. Found OK. Test wiper motor with power to check for proper operation. Found wiper motor inop. Track down and order new wiper motor. Extract water from washer fluid tank. Remove existing washer motor. Clean mounting surface. Install new wiper motor. Found wiring to wiper motor had a bad ground. Wire in new ground. Check motor for proper operation.</p> <p>Found washer hose fitting at drivers side cowl missing. Remove wiper arms. Remove cowl to gain access to washer hose. Found wiper hose disconnected under cowl. Attempt to locate proper replacement part for cowl pass through. Unable to locate part. Install T-fitting and new hose. Remove and replace wiper blades. Route washer hose and install cowl. Reinstall wiper arms. Connect washer hose. Check for proper operation. Found washer and wipers operating as normal.</p> <p>Order new wiper switch knob. Clean up tools and area. Repair complete. - Completed: 12/12/2023</p>			
Parts	PRO-TECH NYTREX TERMINAL 22-18 1/4 FEMALE QS	1.00000	\$2.24	\$2.24
Parts	VALVE 1/4FP 500PSI MINI VALVE	1.00000	\$18.345	\$18.35
Parts	PRO TECH NYTREX TERMINAL 1/4 RING	1.00000	\$2.24	\$2.24
Parts	SHELL ROTELLA 15W-40	18.00000	\$6.495	\$116.91
Parts	Trans Fluid 1-Gallon	0.50000	\$40.5855	\$20.29
Parts	OIL FILTER	2.00000	\$26.67	\$53.34
Parts	FUEL FILTER	1.00000	\$16.215	\$16.22
Parts	FUEL FILTER	1.00000	\$51.011	\$51.01
Parts	AIR FILTER	1.00000	\$95.439	\$95.44
Parts	PUMP	1.00000	\$34.485	\$34.49
Parts	VAC TUBING	5.00000	\$1.08	\$5.40
Parts	WIPER BLADE	2.00000	\$12.2325	\$24.47
Parts	1 GAL ANTIFREZ	1.00000	\$23.985	\$23.99
Parts	WIPER SWITCH	1.00000	\$49.8365	\$49.84
			<b>Subtotal</b>	<b>\$1,564.03</b>

Item	Description	Quantity	Rate	Amount
<b>Complaint:</b> Diagnose and Repair INOP Lights				
<b>Cause:</b> Customer request (Inspection)				
Labor	<b>Correction:</b> Electrical System / Tail/Cab/Marker Lights / Check fuses associated with light operation. Found 30 amp fuse blown. Remove and replace fuse. Found marker lights came on. Found right front fender light inop. Found center cab marker light inop. Remove lens on fender light to gain access to bulbs. Found bulbs OK. Check for voltage at bulb socket. Found correct voltage. Remove light. Found Melted wires and plastic inside light housing. Track down replacement light. Install new light. Wire in new light and secure wiring. Found light operation to be intermittent. Inspect wiring. Found Plug on passenger side loose. Disconnect plug and clean out. Apply dielectric grease to plug. Connect plug and test. Found normal operation.  Remove center marker light lens. Found bulb burned out. Install new bulb. Check for proper operation. Found all OK. Clean up tools and area. Repair complete. - Completed: 12/8/2023	2.07000	\$145.00	\$300.15
Parts	194 Light Bulb	1.00000	\$1.137	\$1.14
Parts	16-14 AWG BLUE CRIMP & SEAL BUTT CONNECTORS	3.00000	\$0.981	\$2.94
Parts	M8(5.6")-1.25 METRIC FINISHED HEX FULL NUTS	1.00000	\$0.1878	\$0.19
Parts	7" 50LB NYLON CABLE TIE	1.00000	\$0.2175	\$0.22
Parts	36 LED R.H	1.00000	\$62.582	\$62.58
			<b>Subtotal</b>	\$367.22
HAZMAT DISPOSAL FEE		1.00	\$15.00	\$15.00

**Unit:** N/A **VIN:** 1HTAA1859BHA19809  
1981 International 1824, 1854  
**Chassis:** 119,618 Miles

<b>Labor</b>	\$1,719.95
<b>Parts</b>	\$581.30
<b>Service Call</b>	\$175.00
<b>Mileage</b>	\$5.50
<b>Shop Supplies</b>	\$104.10
<b>Pre-Charge Subtotal</b>	\$2,585.85
<b>HAZMAT DISPOSAL FEE</b>	\$15.00
<b>Local</b> (6% of \$685.40)	\$41.12
<b>Total</b>	\$2,641.97
<b>Payments &amp; Credits</b>	\$2,641.97
<b>Balance Due</b>	\$0.00

## Payment Information

Date	Payment #	Method	Reference #	Amount
12/13/2023	5344885	Check	CHECK #3195	\$2,641.97

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. An 18% finance charge will be added to any invoice past due 14 days, and then each additional 14 days thereafter.

**PAYMENT IS DUE AT THE TIME OF SERVICE.**

Customer Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Date: \_\_\_\_\_